KENOTEK

HOW TO USE KENOTEK CARGO 4100

- Dilute Kenotek Cargo 4100 4:1 with water (four parts water and one part Kenotek).
 - Apply mixed solution to vehicle using snow foam gun/device (if cleaning a larger vehicle you may wish to do one side at a time).
- Leave the solution to work for 4-5 minutes on the vehicle.



- Jet wash off the solution using the following technique:
 - 1. Always start at the bottom and work your way up.
 - 2. Jet wash off using a side to side motion (imagine painting a fence panel).
 - 3. Make sure you get all areas of the truck with the jet wash as this is replacing brushing or sponging.
- Rinse off any excess solution once all dirt is removed.
- Leave to dry. DO NOT RUB WITH HANDS OR A CLOTH.

For any queries please contact us
Call: 07949226181
Email: info@joeboothtransport.co.uk

